




LAYOUT DIAGRAM OF RANDOM ASSEMBLY WINDER (Model: VJAW-6)



Number of spindles	10	20	30	40	50	60	70	80	90	100
Length (mm)	2676	4852	7028	9204	11380	13556	15732	17908	20084	22260